GENERAL INDEX.

[NOTE.—Authors' and Speakers' names in SMALL CAPS.: Titles of Papers in *italics.*]

	PAGE
Air Space, efficiency of	103
American Association for the Advancement of Science	29
American Machinery at International Exhibitions, T. R. Pickering	113
ANGSTROM, C., *New Valve Motion*	41
Annealing Furnace for Copper	150
Annual Meeting, 1883	3
Anvils for Drop Press	60
Appendix on Natural Gas	340
" to Estimates for Steam Users	290
Babbitt Metal, composition of	153
BARNES, P., disc. Power Crane	138
BARR, W. M., disc. New Valve Motion	46
" " " Non-conducting Coverings	107
BARRUS, G. H., *Comparison of Three Modern Types of Indicators*	310
BOGART, J., A. S. C. E., on Test Commission	12
Boiler Tests, Rules for Conducting, W. Kent	260
BOND, G. M., disc. Drop Press	62
" " " Perfect Screw	243
Bramah's lock	124
BRASHEAR, J. W., disc. Perfect Screw	257
Brass, Manufacture of	148
Bridge at Grenoble	111
Brown's Testing Device	317
" Valve Motion	46
Burnishing of Copper Rolls	155
Car Springs	189
Charcoal, Combustibility of	101
CLOUD, J. W., *Helical Springs*	173
COLE, J. W., disc. Estimates for Steam Users	298
Committee, Local, New York, 1883	3
" " Pittsburgh, 1884	159
" on Holley Memorial Report	15
" " Invitation of Foreign Engineers	17
" " Rules for Conducting Boiler Tests	170
" Test Commission Report	9
" to Nominate Officers, 1884	162
" Revision of Rules Report	164
Communication on Uniform Standards for Test Specimens	164
Comparison of Three Modern Types of Indicators, G. H. Barrus	310
Compression as a Method of Governing, H. Tabor	48

PAGE
Condensation in Long Steam Pipes.... 106
Copper Castings, Flux for.... 152
" " Color of.... 154
COUCH, A. B., disc. Drop Press.... 61
Crane, A Power, W. F. Durfee.... 131
Cut-off Valves, Motion Curves of, A. W. Robinson.... 34

DEMPSTER, ——, disc. Natural Gas.... 375
Dephosphorization of Iron by Natural Gas.... 365
Drawing Office System, H. R. Towne.... 193
Drop Press, Pressure Obtainable by the Use of, R. H. Thurston.... 53
Drop Presses, Heavy versus Light.... 59
" " efficiency of.... 54
Dues, annual, increase of.... 17
DURFEE, W. F., *A Power Crane*.... 131
" " disc. Properties of Metals and Alloys.... 147
" " " Perfect Screw.... 256
" " " Natural Gas.... 367

Efficiency of the Drop Press.... 54
EGLESTON, T., *Machine for Testing Physical Properties of Metals and Alloys*. 140
" " disc. Non-conducting Coverings.... 111
Ejector for Supplying Natural Gas.... 367
Elutriated Powders for Grinding.... 258
EMERY, CHARLES E., *Estimates for Steam Users*.... 282
" " disc. Water Meter.... 69
" " " Non-conducting Coverings.... 103
" " " Machinery at International Exhibitions.... 122
" " " Helical Springs.... 191
" " " Drawing Office System.... 204
" " " Perfect Screw Problem.... 256
" " " Rules for Boiler Tests.... 270
" " " New York to Chicago in 17 Hours.... 305
" " " Indicators.... 336
Estimates for Steam Users, Charles E. Emery.... 282
Exhibitions, Amer. Mach. at International.... 113
Experiments upon Non-conducting Coverings for Steam Pipes, J. M. Ordway.... 73, 212

Fatigue of Metals.... 154
Fires caused by Pipe Coverings.... 102
Flow of Metals under Drop Press.... 59
Formula of Steam for Engines.... 293
" " " " Hydraulic Elevators.... 294
" " " " Pumps.... 294
" " " " Steam Elevators.... 295
" " " " Heating Water.... 295
" " " " Jets.... 295
French Locks.... 128
Friction of Drop Press.... 60, 62
" " the Indicator.... 333

PAGE
Gas as Steam Fuel 345, 360
Gas Engines 345
Gowing's Drum Testing Device 320
GRANT, J. J., disc. Drop Press 62
" " " Properties of Metals and Alloys 147
Graphic Method in Boiler Tests 274
Grenoble Bridge 111
GRIMSHAW, ROBERT, disc. Water Meter 68
" " " Non-conducting Coverings 102
" " " Machinery at International Exhibitions 123
" " " Properties of Metals and Alloys 152
Grinding of Screws 244

HAND, S. A., disc. Perfect Screw 241
" " " Indicators 333
Helical Springs, J. W. Cloud 173
HENNING, G. C., disc. Natural Gas 369
HIGGINS, M. P., disc. Drop Press 60
HOADLEY, J. C., *Tilting Water Meter for Purposes of Experiment* 63
HOBBS, A. C., disc. Machinery at International Exhibitions 123
" " " Properties of Metals and Alloys 148
HOLLOWAY, J. F., disc. Non-conducting Coverings 109
" " " Machinery at Internat. Exhibitions 122
" " " Indicators 336
Horse-power of Boilers 284
HUNT, A. E., disc. Natural Gas 364

Indicators, Comparison of Three Types of, G. H. Barrus 310
International Exhibitions, American Machinery at, T. R. Pickering 113
Introduction to Non-conducting Coverings, C. J. H. Woodbury 72
Isherwood's Experiments on Non-conducting Coverings 108

JARBOE, W. S., disc. Natural Gas 361
JONES, W. R., disc. Natural Gas 366
Joy's Valve Gear 47

Kal defined 282
KENNEDY, J., disc. Non-conducting Coverings 112
KENT, W., *Rules for Conducting Boiler Tests* 260
" " disc. Non-conducting Coverings 111
" " " Perfect Screw 249
" " " Estimates for Steam Users 296
" " " New York to Chicago in 17 Hours 307
" " " Indicators 336
" " " Natural Gas 360
KIRCHHOFF, C., disc. Natural Gas 375

LEAVITT, E. D., disc. Water Meter 71
" " " Non-conducting Coverings 108
" " " Machinery at International Exhibitions 121
" " " Properties of Metals and Alloys 152

PAGE

LEAVITT, E. D., disc. Rules for Conducting Boiler Tests..... 277
" " " Estimates for Steam Users..... 297
" " " New York to Chicago in 17 Hours..... 306
LE VAN, W. B., *New York to Chicago in 17 Hours*..... 301
" " disc. Rules for Boiler Tests..... 268
" " " Estimates for Steam Users..... 299
" " " Indicators..... 335
Local Committee, N. Y., 1883..... 3
" " Pittsburgh, 1884..... 159
Locomotive Cylinders, Cut-off Valves for..... 305
" " Port Areas of..... 308
" " Size of..... 305
" Engine of G. H. Corliss..... 306

Machine for Testing Physical Properties of Metals and Alloys, T. Egleston... 140
Machinery, American, at International Exhibitions..... 113
Marshall's Valve Gear..... 45
Master Tap for Perfect Screw..... 254
Measuring Machines..... 242
Mercury Well in Feed Pipe..... 71
METCALF, W., disc. Helical Springs..... 185
" " " Natural Gas..... 362
Mineral Wool as Non-conductor..... 105
Molecular Structure of Steel..... 245
MORGAN, T. R., disc. Drop Press..... 60
MORTON, H., disc. Natural Gas..... 374
Motion Curves of Cut-off Valves, A. W. Robinson..... 34

NAGLE, A. F., disc. Rules for Boiler Tests..... 275
Natural Gas as Motive Power.....365, 367
" " as Steam Fuel..... 345
" " Combustibility of..... 350
" " Cost of.....345, 364
" " Danger of..... 350
" " In Iron Manufacture..... ....345, 362, 364, 365, 367
" " Odor of 375
" " Pipes for.....348, 371
" " Properties of..... 357
" " Wells..... 343
" " Laws of Pennsylvania on..... 352
" " Pressure of..... 349
New Valve Motion, C. Angstrom..... 41
New York to Chicago in 17 Hours, W. B. Le Van 301
Non-conducting Coverings for Steam Pipes, J. M. Ordway, 1st paper..... 73
" " " " " 2d paper..... 212
Novelty Iron Works Experiments..... 337

ODELL, W. H., disc. Water Meter..... 69
ORDWAY, J. M., *Non-conducting Coverings for Steam Pipes*, 1st paper..... 73
" " " " " 2d paper..... 212

PAGE
PAINTER, P., disc. Natural Gas 367
PARTRIDGE, W. E., disc. Water Meter 70
Perfect Screw Problem, Practical Solution of, W. A. Rogers 216
Permanence of Metals 250
PICKERING, T. R., *Am. Machinery at International Exhibitions* 113
Pipe-joints for Natural Gas 348, 371
Plaster of Paris as Non-conducting Covering 108
PORTER, C. T., disc. Water Meter 71
" " " Perfect Screw 252
" " " Rules for Boiler Tests 276
" " " Indicators 331
Positive Speed Indicator, O. Smith 206
Power Crane, A, W. F. Durfee 131
" " at Novelty Works 138
" " at Joliet 138
Practical Solution of the Perfect Screw Problem, W. A. Rogers 216
PRATT, N. W., disc Rules for Boiler Tests 269
Pressure Obtainable by the Use of the Drop Press, R. H. Thurston 53
Proceedings New York Meeting, 1883 3
" Pittsburgh Meeting, 1884 159
Properties, Physical, of Metals and Alloys, T. Egleston 140

REESE, J., disc. Perfect Screw 245
" " " Natural Gas 364
Report of Council, November, 1883 7
" " " May, 1884 162
" " Committee on Test Commission 9
" " " " Holley Memorial 15
" on Revision of Rules 16, 164
" of Tellers, November, 1883 21
" " " May, 1884 165
" " Treasurer, Nov., 1883 7
" " " May, 1884 163
" on Natural Gas 340
Resolutions of Thanks, Nov., 1883 31
" " " May, 1884 171
ROBERTS, T. P., disc. Natural Gas 363
ROBINSON, A. WELLS, *Motion Curves of Cut-off Valves* 34
ROBINSON, S. W., disc. Perfect Screw 250
" " " Indicators 333
ROGERS, W. A., *Practical Solution of the Perfect Screw Problem* 216
ROSS, ANDREW, Dividing Engine 256
Rules for Conducting Boiler Tests, W. Kent 260

Screw, Perfect 216
Screws, Standard 220
" for Lathes 236, 241, 249
Siemens Furnace in Brass Manufacture 149
SMITH, O., *Positive Speed Indicator* 206
" " disc. Drop Press 59
" " " Water Meter 68

PAGE

SMITH, O., disc. Non-conducting Coverings 109
" " " Properties of Metals and Alloys 147
" " " Helical Springs 184
" " " Perfect Screw 236, 254
Solution, Practical, of Perfect Screw Problem, W. A. Rogers 216
Speed Indicator, Positive, O. Smith 206
Springs, Helical, J. W. Cloud 173
Steam for Elevator Engine 289
" " Heating 291
" " Factory Engine 292
" " Pumps 294
" " Jets 295
Steam Pressures, usual 269
Steam Users, Estimates for 282
STRONG, G. S., disc. New Valve Motion 46
" " " Natural Gas 369
" " " Water Meter 71
" " " Machinery at Internat. Exhibitions 122
SWEET, J. E., disc. Perfect Screw 242

Table of Distortion of Indicator Diagrams 328
" " Areas of " " 330
" " Non-conducting Coverings for Steam Pipes 95
" " Pressures under Drop Press 54
" " Steam per H. P 51
" " " used in Engines 288
" " Tests of Spring Steel 174
" " Weights, etc., of Indicators 313
" " Errors of Springs of Indicators 316
" " Tension of Drum Springs 320
TABOR, H., *Compression as a Method of Governing* 48
Temperature affecting Standard Bars 247
Tempering of Steel Springs 184
Tests of Springs 187
Thermal unit as Standard of Evaporation 298
Thermometers for Feed Water 71
THURSTON, R. H., *Pressure Obtainable by Use of the Drop Press* 53
" " disc. New Valve Motion 45
" " " Non-conducting Coverings 101
Tilting Water Meter for Purposes of Experiment, J. C. Hoadley 63
Time of Oscillation of Spring 183
TOWNE, H. R., *Drawing Office System* 193
" " disc. Drop Press 58
" " " Power Crane 138
" " " Properties of Metals and Alloys 147
" " " Perfect Screw 236
" " " Natural Gas 371
Tubular Springs 191

Unit of Commercial Evaporation 300
" " Evaporation 284

PAGE

Valve Motion, New, C. Angstrom 41

WALKER, J., disc. Drawing Office System 204
Water Meter, Tilting, J. C. Hoadley 63
" " Errors of 69
" Evaporated by Gas Fuel 361
Wearing Surfaces of Screws and Nuts 242
WEBB, J. B., disc. Drop Press 58
" " " Helical Springs 185
" " " Drawing Office System 205
" " " Perfect Screw 241
" " " Rules for Conducting Boiler Tests 277
" " " Natural Gas 374
WEBBER, S., disc. Properties of Metals and Alloys 154
Weighing Feed Water for Locomotives 71
Weight of Water by Volume 70
" " Steam by Volume 286
WOLFF, A. R., disc. Water Meter 72
WOODBURY, C. J. H., Introduction to Non-conducting Coverings 73
" " disc. Non-conducting Coverings 110
" " " Perfect Screw 248
" " " Rules for Boiler Tests 274